

CLASSIFY TO FILE NO.

X-REF TO FILE NO.

FILE RID ☐ RET. TO BRANCH ☐

DESTROY ☐ SIG.

SECRET

GROUP 1
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

REPRODUCTION PROHIBITED

PERSON/UNIT NOTIFIED

1		5	RE
2		6	RE
3		7	SD
4		8	

FROM

DISSEM BY 53

ACTION

LOGS

☐ RID COPY

ADVANCE COPY

☐ ISSUED

☐ SLOTTED

☐ TUBED

UNIT

TIME

BY

INFO

FILE, VR, FE

ACTION

4 JUN 66 12 30709

25X1A

25X1A

SECRET 040219Z CITE

LOGISTICS INFO DIRECTOR

25X1A

SENDS

25X1A

25X1A

CAUSED BURN OUT ONE OF TWO SINGLE PHASE REGULATORS. MUST REPLACE CORE SOONEST EST COST

25X1A

\$1500. STRONGLY RECOMMEND REPLACE BOTH SINGLES WITH 3 PHASE REGULATOR MAINLY AS WE NOW NEAR NAMEPLATE AMP RATING. EST COT \$9600. FUNDS ARE AVAILABLE. WOULD HOPE FOR

25X1A

PROCUREMENT OR SHIPMENT.

25X1A

DURING SAME PERIOD ONE 300 KW STANDBY GENERATOR ARCED OUT REQUIRING REBUILD WHICH WE CAN DO WITH SPARE PARTS ON HAND.

25X1A

REQUEST RE AND CD EVALUATION

25X1A

ADVISABILITY PARA 1 PROPOSAL AND WOULD APPRECIATE DETERMINE IF POSSIBLE TO UP RATE CATERPILLAR D-397 BY ENGINE MODIFICATION AND INSTALLATION NEW HIGH TEMPERATURE GENERATOR INSULATION. IF POSSIBLE WHAT COST. AM SURE YOU REALIZE WE NEED EXPEDITIOUS REPLY WITH ONE GENERATOR DOWN AND ONLY ONE REGULATOR.

SECRET

BT

SECRET

C/REC
2 DC/REC
1 EDC
C/ACQ
3 C/CD
4 C/UE
SEEK RTN + DBM
CENTRAL FILE
FILE